ISSN No:-2456-2165

Defect Analysis of Building Construction Works Building in Surabaya with Six Sigma Method

Wawan Kristanto Dept. Management of Technology Institute Technology of Sepuluh November, ITS Surabaya, Indonesia

Abstract:- In the process of construction defect issue work hard to avoid even happens repeatedly, it causes swelling of the cost and time of implementation. In a previous study concluded that the cost of repairs due to defects employment of 4% of the value of construction contracts. The purpose of this study is to identify the types of defects based on the level of sigma and analyze variables and simulating the cause of defect repair recommendations for improving sigma level. In identifying and analyzing defects used six sigma method work through several stages of the Define, Measure, Analysis, Improve and Control. The results of this study showed 14 types of defect construction work, from some defect that there are two types of defects jobs require increased sigma level, because it is below the level of three sigma. The first defect type is a porous structure with concrete columns sigma level of 2.75 and a variable that has a high influence is less than perfect compaction when casting. The second type is the distance point defect piles not according to plan with sigma levels 2,86 and variables that most influence is the lack of communication with the consultant planner and owner. Based on the simulation recommendation defect corrective action on concrete columns porous structure, resulting in improved sigma level of 3.63 when the eighth recommendation implemented. At the distance of a point defect pile foundation is not according to plan, after the simulation of recommendations for improvement sigma level to 3.48.

Keywords:- building construction work defects; six sigma level; quality function deployment; Monte Carlo simulation.

I. BACKGROUND

Imperfections result of construction work is a problem which can reduce the quality of the work, it must be quickly resolved so that the quality of work as expected. All efforts made by the central government and the local governments by issuing several regulations in the field of construction, but still imperfections or defects in construction are still common.

In law no.2 in 2017 on construction services that the construction sector is building a community that serves as a consummate, or infrastructure support social and economic activities of society in order to support the realization of national development goals, as well as construction services must ensure order and legal certainty. Often construction projects suffered imperfections result of the work during construction or upon delivery of the implementation of the interim results of the work to the owner. In the process of construction work difficult jobs defect problems to be avoided

I Putu Artama Wiguna Dept. Management of Technology Institute Technology of Sepuluh November, ITS Surabaya, Indonesia

even happens repeatedly, it causes swelling of the cost and time of execution (Sik Park et. Al, 2013).

Problems resulting from construction defects caused economic losses and can reduce the trust between the various stakeholders. In a previous study concluded that the cost of repairs due to defects employment of 4% of the value of construction. This research is about the kind of work the defects that occur in construction projects based on sigma level, so we know the quality of work kontrtuksi and simulate sigma level increase based on recommendations for improvement.

II. LITERATURE REVIEW

- A. Construction defect
- Understanding the Construction Defect

In Black "s Law Dictionary (7th edition) defines" defect "which means" imperfections or deficiencies ". The term "imperfections" in ISO 9000: 2005 is a failure to meet a requirement. In the construction industry we often see the words' imperfections or deficiencies "in a job. In Indonesia itself has issued Government Regulation No. 29 of 2000 on the implementation of construction services in this Regulation defines the failure of the construction works is the state of the construction work that is not in accordance with the specification of work, as agreed in the contract construction work either in part or in whole as a result of user error services or service providers.

• Categories On the Construction Defect

Basically all forms of work are qualitative defect in which the judgment is based on quality pekerejaan generated, construction defect nature of the category itself is categorized into two, namely: a defect that is patent and the defect is latent (Barrett, 2008).

• Defect Patent

Patent defects are defects that looks directly to the eye and the degree of visibility that the lead role in analyzing the defect of a work (Barrett, 2008).

• Latent defect

Latent defect is a hidden defect and difficult job to be identified. Usually this kind of new defects identified after further investigation of the defect previously unknown work.

B. Construction Defect Causes

In the process of the construction work of the defect is difficult to avoid considering a construction project has a broad scope of work, which consists of several sub-units of work. The cause of the construction defect can be caused by one of the parties involved in the construction activities. For

ISSN No:-2456-2165

the realization of a building that gives satisfaction to consumers or users of the building, then the conditions that must achieve three things, among others: good workmanship during the construction process, materials or materials used in accordance with the requirements of good design and quality (Barrett, 2008). The root cause of the defect of construction generally determine the origin of the cause, and the defect factors, among others: Design, Work Processes, Materials and Maintenance (Chong et. Al 2006).

In another study said the main causes of construction defects are categorized into three types: design error, error workmanship and quality of materials used (Merhaba, 2015). By reviewing some of the references above about the cause of the defect of construction, should pay attention to several aspects including: Aspect Design, Process Aspects Construction, Materials Aspect, Aspect Maintenance.

• Design aspects

Design is a very important part in the development of projects to be undertaken padasuatu and affect the construction of a building, in other words the quality of a building is determined at the initial design (Ahzahar et. Al 2006).

• Aspects of the Construction Process

Construction work experiencing a job imperfections can be defined as work that does not meet the requirements of the agreed contract (Sabha, 2015).

• Material aspects

Selection of a material must meet the expected requirements, using poor quality materials will cause poor quality buildings. Selection of materials should be in accordance with the requirements of the specification in order to minimize the costs incurred during the maintenance phase (Hassanain et. Al, 2013).

• Aspect Maintenance

The success of a project depends on the performance, as measured by the cost of maintenance and the quality of workmanship standards, therefore the maintenance costs can be more expensive than the initial fee if the maintenance costs are not included during the planning stage (Femi, 2014).

III. RESEARCH METHODOLOGY

Quantitative research approach characterized by descriptive, where penedekatan is used as a theme or objects associated with the studies reviewed the state of empirical research sites. In the method of data collection used questionnaires, interviews and documentation obtained from the supervising consultant. In identifying and analyzing defects used six sigma method work through several stages Define, Measure, Analysis, Improve and Control.

IV. RESULTS AND DISCUSSION

A. Define phase

In this phase, the first stage in improving the quality, by defining and identifying the types of defects that occur in construction projects. In this study, which form the object of study consists of 15 construction projects, from the analysis identified 14 types of defects that construction work can be seen in the following table:

		Total	Total
	ofact Trine Construction Work		Number of
	efect Type Construction Work	Defe	
		ct	Jobs
Α	Defect Foundation Work		
1	Distance point pile not	43	468 (group)
	according to plan		
2	The depth of the foundation is	8	468 (group)
2	not according to plan	0	100 (group)
3		11	169 (2000)
3	Poles have cracks when lining	11	468 (group)
В	Defect At Work Concrete		
	Columns		
4	Column formwork when	33	1200 (point)
	casting the concrete structure		· · ·
	uncovered		
5	Concrete columns porous	126	1200 (point)
5	structure after casting	120	1200 (point)
6	Concrete column is not	45	1200 (point)
0	symmetric	15	1200 (point)
7	The length distribution	39	1200 (point)
/	(continued) column	39	1200 (point)
	reinforcement is less than the		
	standard		
С	Defect At Work Concrete		
	Beams		
8	Beam formwork when casting	52.8	10377.48
	the concrete structure		(m ¹)
	uncovered		
9	Porous concrete block structure	196.	10377.48
	after casting	7	(m ¹)
	6		~ /
10	Deflection occurs on the beam	126.	10377.48
10	Deneedion occurs on the occurs	5	(m ¹)
		5	(111)
11	The length distribution	156.	10377.48
11	(connection) less than the	130. 75	(m^1)
		15	(111-)
D	standard beam reinforcement		
D	Defect At Work Concrete		
	Beams		
12	Porous structure of the	84.2	11780.5 (m ²)
	concrete slab after casting	5	
13	Deflection occurs at plate	35	11780.5 (m ²)
14	Having split the concrete slab	44	11780.5 (m ²)

 Table 1. Type of construction work defects

B. Phase Measure

After pendifinisian issues to be analyzed, the next step is to measure the phase by measuring baseline measurement of performance and process capability.

1. Performance Measurement Baseline

In this study the performance baseline measurement is done by using parameters Defect Per Million (DPMO), and this value can be known DPMO sigma value of each type of defect construction work following calculation example:

• Distance point foundation in not according to plan

$$DPMO = \frac{43}{468} \times 1.000.000 = 91880,34 \tag{1}$$

Sigma value calculation:

From the above calculation obtained DPMO value of 91880.34, because the value is between 96800 (2.8 sigma level) and 80800 (2.9 sigma level) with respect to the conversion table sigma value, the sigma value calculation to be accurate to do by interpolation based on both values. To see the value of DPMO and sigma level of each defect type of construction works, can be seen in the following table:

D	efect Type Construction Work	Sigma	DPMO
D	elect Type Construction Work	value	value
1	Distance point pile not according to plan	2,86	91880.34
2	The depth of the foundation is not according to plan	3.68	17094.02
3	Poles have cracks when lining	3.41	23304.27
4	Column formwork when casting the concrete structure uncovered	3.48	27500
5	Porous concrete column structure after casting	2.75	105000
6	Concrete column is not symmetric	3.22	37500
7	The length distribution (continued) column reinforcement is less than the standard	3.35	32500
8	Beam formwork when casting the concrete structure uncovered	4.04	5293.88
9	Porous concrete block structure after casting	3.54	19721.71
10	Deflection occurs on the beam	3.76	12683.26
11	The length distribution (connection) less than the standard beam reinforcement	3.75	15716.21
12	Porous concrete slab structure after casting	3.95	7151.65
13	Deflection occurs at plate	4.25	2971.01
14	Having split the concrete slab	4.12	3734.99

Table 2. Value of DPMO type of defect construction work

In the above table 2 can be seen the value of the lowest in the defect 5 sigma concrete columns porous structure after casting (sigma level 2.75) and followed defect pile 1 Distance point not according to plan. (2.86 sigma level). In a spread value DPMO facilitate viewing of each defect, then made the radar chart as shown below:




Fig 1:- Distribution of value DPMO type of defect

2. Measurement Process Capability

This measurement is taken on the type of defect is a defect analyzed the structure of porous concrete column 5 after casting (2.75 sigma level) and defect 1 Distance point pile is not as planned (2.86 sigma level). Since both types of defects are located below the industry average. In this study specification upper value limits (USL) is derived from the value of level 3 with defect specification 0.0667% and lower limits (LSL) is derived from the value of level 4 with defect 0.0062%.

 Measurement Capability defect porous structure of concrete columns




Fig 2:- Capability analysis binomial defect porous structure of concrete columns

• Measurement Capabilities within a point defect piles not according to plan




Fig 3:- Capability analysis binomial defect within a point of foundation

In the graph P chart we can see that from the 15 observation data is still at a value between UCL and LCL, the process is statistically under controlled conditions. But there are some points that came out of specification limits between LSL and USL.

On cumulative% defective chart is marked by instability along the line% defective average. Thus samples taken representative and reliable enough to describe the actual process Performance.

From the graph above the rate of defective can dilihat% randomly distributed around the center line, it can be concluded that the data follows a binomial distribution.

Histogram graph above shows that the existing process is not stable enough to produce a good product, because most of the stem the histogram is dikanan target value.

C. Phase Analysis

The purpose of this phase is to analyze the root causes that cause problems in the production process. Factors that cause the defect obtained from the collection of questionnaires by respondents team leader and chief inspector on the project. The results of this questionnaire using descriptive analysis that has been tested statistically, the following table analyzes the results of the causal factors:

No.	Factors defect porous concrete	mean	Std.	Ran
	column structure		dev	k
Q16	Compaction less than perfect when casting	4.133	0.833 1	1
Q15	High-falling concrete at the time of casting	4.067	0.798 1	2
Q14	Concrete cover on the column is too thin	4,000	0.845	3
Q9	The lack of experience of labor used	4,000	1.133 8	4
Q17	Air cement out of the mold formwork	3,800	1.014 1	5

• Factors causing defect porous structure of concrete columns

	ISSN No:-2456-2					
No.	Factors defect porous concrete column structure	mean	Std. dev	Ran k		
Q4	Non-compliance and working procedures	3,800	1.082 3	6		
Q7	Lack of expertise implementers	3,733	0.961 1	7		
Q13	Usage column formwork more than 3 times the wear	3,667	1.112 7	8		
Q12	Too quickly dismantle the formwork	3,667	1.234 4	9		
Q10	Lack of teamwork	3,600	0.828 0	10		
Q3	Lack of commitment to quality assurance and quality control	3.533	0.990 4	11		
Q18	Pouring concrete material from the mixer too long Trux	3,333	0.899 7	12		
Q2	Ignore the request and instruction owner	3.133	0.915 4	13		
Q6	Lack komunakasi with planning consultant and owner	3.133	0.915 4	14		
Q1	Lack of periodic checks during the process of construction	3.133	1.125 4	15		
Q11	Use of equipment (vibrators) are not according to the standard procedure	3.133	1.187 2	16		
Q8	Too fast in execution to avoid delays	3.133	1.187 2	17		
Q5	The workers can not understand the working drawings	2,067	1.162 9	18		

 Table 3. Mean and Standard Deviation Factor defect porous concrete column structure




Fig 4:- Diagram of Mean - Standard Deviation defect factor porous structure of concrete columns

In the picture above shows that each variable groups in mean values between 3 and 4, so that it can be described average respondent answered quite agree and agree that each variable affects the defect porous concrete column structure. • Factors causing the defect within a point of foundation

No.Factors pile defect distance point is not according to planmeanStd.Ran devQ6Lack komunakasi with planning consultant and owner4.0670.9611Q5Piling equipment operator can not understand the working drawings4,0001,0692Q8Too fast in execution to avoid delays4,0001,1953Q4Non-compliance and working procedures3.9330.7044No.Factors pile defect distance point is not according to planmeanStd.Ran devQ9Operator tool used.3.9330.5945Q13Not ratanya land surface area of the location of erection (erection sequence number)3.8670.6406Q14simulation plan drawing tool on erection3.7330.8848Q2Ignore the request and instruction owner3.7330.5949Q10Coordination of field workers3.6670.81610Q3quality assurance and quality control3.6670.72411Q14Lack of commitment to quality assurance and quality control3.4000.91012Q15Lack of periodic checks quality assurance of construction3.3330.72414Q16Lack of periodic checks construction3.3330.72414Q17Lack of periodic checks construction3.3330.72414Q18Lack of periodic checks quality assurance and puality construction3.333 <t< th=""><th></th><th></th><th></th><th></th><th>1</th></t<>					1	
Lack komunakasi with planning consultant and owner4.0670.9611Q6Piling equipment operator can not understand the working drawings4,0001,0692Q8Too fast in execution to avoid delays4,0001,1953Q4Non-compliance and working procedures3.9330.7044No.Factors pile defect distance point is not according to planmeanStd. devRan kkQ9Operator tool used.3.9330.5945Q13Not ratanya land surface area of the location of erection3.8670.6406Q14Ess detailed determination of the sequence As erection (erection sequence number)3,7330.8848Q2Ignore the request and instruction owner3,7330.5949Q10Lack of teamwork and coordination of field workers3,6670,81610Q3Quality assurance and quality control3,4000.91012Q12Pemancang tool that he was already old3,4000.98613Q13Lack of periodic checks during the process of construction3,3330.72414Q14Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3330.97615	No.	Factors pile defect distance	mean	Std.	Ran	
Q6 ownerplanning consultant and owner4.0670.9611Q5Piling equipment operator can not understand the working drawings4,0001,0692Q8Too fast in execution to avoid delays4,0001,1953Q4Non-compliance and working procedures3.9330.7044N0.Factors pile defect distance operator tool used.mean devStd. kRan devQ9The lack of experience of the operator tool used.3.8670.6406Q13Not ratanya land surface area of the location of erection3.8670.6406Q15the sequence As erection (erection sequence number)3,7330.8848Q2Ignore the request and instruction owner3,7330.5949Q10Coordination of field workers coordination of field workers3,6670,81610Q12Pemacang tool that he was already old3,4000.91012Q14Lack of commitment to quality assurance and quality control3,3330.72414Q16Lacks of periodic checks during the process of construction3,3330,72414Q14Pemacangan tool that responding coordinates control3,3330,72414Q12Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3000,97615				dev	k	
ownerownerownerQ5Piling equipment operator can not understand the working drawings4,0001,0692Q8Too fast in execution to avoid delays4,0001,1953Q4Non-compliance and working procedures3.9330.7044No.Factors pile defect distance operator tool used.mean 3.933Std. devRan devQ9The lack of experience of the operator tool used.3.8670.6406Q13Not ratanya land surface area of the location of erection (erection sequence number)3,8000.6767Q14Ess detailed determination of instruction owner3,7330.5949Q10Ignore the request and coordination of field workers3,6670,81610Q12Pemancang tool that he was already old3,4000.91012Q13Permancang tool that he was already old3,4000.98613Q14Lack of periodic checks construction3,4000.91012Q15Less details Setting Out point control3,3330.72414Q14Permacangan tool that treatment is less so the accuracy and precision are not appropriate3,3030.97615						
Q5Piling equipment operator can not understand the working drawings4,0001,0692Q8Too fast in execution to avoid delays4,0001,1953Q4Non-compliance and working procedures3.9330.7044No.Factors pile defect distance opint is not according to planmeanStd. devRan devQ9The lack of experience of the operator tool used.3.9330.5945Q13Not ratanya land surface area of the location of erection (erection sequence As erection (erection sequence number))3,8000.6767Q14Ignore the request and instruction owner3,7330.5949Q10Lack of teamwork and coordination of field workers3,6670,81610Q3quality assurance and quality control3,6670.72411Q12Pemancang tool that he was already old3,4000.91012Q14Lack of periodic checks during the process of construction3,4000.98613Q15Less details Setting Out point corresponding coordinates stake3,3330.72414	Q6	planning consultant and	4.067	0.961	1	
Q5 not understand the working drawings4,0001,0692Q8Too fast in execution to avoid delays4,0001,1953Q4Non-compliance and working procedures3.9330.7044No.Factors pile defect distance operator tool used.meanStd. devRan devQ9The lack of experience of the operator tool used.3.9330.5945Q13Not ratanya land surface area of the location of erection3.8670.6406Q15Less detailed determination of the sequence As erection (erection sequence number)3,7330.8848Q2Ignore the request and instruction owner3,7330.5949Q10Lack of teamwork and coordination of field workers3,6670,81610Q3quality assurance and quality control3,6670.72411Q12Pemancang tool that he was already old3,4000.91012Q16Lack of periodic checks construction3,3330.72414Q16Less details Setting Out point corresponding coordinates stake3,3330.72414Q11Pemaacangan tool that treatment is less so the accuracy and precision are not appropriate3,2000.97516						
drawingsImage: Construction to avoid delays4,0001,1953Q4Non-compliance and working procedures3.9330.7044No.Factors pile defect distance point is not according to planmeanStd.Ran devQ9The lack of experience of the operator tool used.3.9330.5945Q13Not ratanya land surface area of the location of erection3.8670.6406Q15the sequence As erection (erection sequence number)3,7330.8848Q2Ignore the request and instruction owner3,7330.5949Q10Lack of teamwork and coordination of field workers3,6670,81610Q3quality assurance and quality control3,6670.72411Q12Pemancang tool that he was already old3,4000.91012Q14Lack of periodic checks data during the process of construction3,3330.72414Q14Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3330.97615						
Q8Too fast in execution to avoid delays4,0001,1953Q4Non-compliance and working procedures3.9330.7044No.Factors pile defect distance point is not according to planmeanStd. devRan devQ9The lack of experience of the operator tool used.3.9330.5945Q13Not ratanya land surface area of the location of erection3.8670.6406Q15the sequence As erection (erection sequence number)3,8000.6767Q14simulation plan drawing tool on erection3,7330.5949Q10Lack of teamwork and coordination of field workers3,6670,81610Q3quality assurance and quality already old3,6670.72411Q12Pemancang tool that he was already old3,4000.91012Q16Lesk of periodic checks construction3,3330.72414Q17Lack of periodic checks during the process of construction3,3330.72414Q11Pemacang nool that treatment is less so the accuracy and precision are not appropriate3,3200.97615		not understand the working	4,000	1,069	2	
Q8delays4,0001,1953Q4Non-compliance and working procedures3.9330.7044No.Factors pile defect distance point is not according to planmeanStd. devRan kQ9The lack of experience of the operator tool used.3.9330.5945Q13Not ratanya land surface area of the location of erection3.8670.6406Q15Less detailed determination of the sequence As erection (erection sequence number)3,7330.8848Q14Simulation plan drawing tool on erection3,7330.5949Q10Lack of teamwork and coordination of field workers3,6670,81610Q12Pemancang tool that he was already old3,4000.91012Q14Lack of periodic checks during the process of construction3,3330.72414Q16Corresponding coordinates stake3,3330.72414Q11Lack of experise accuracy and precision are not appropriate3,3000.97615		drawings				
Q4Non-compliance and working procedures3.9330.7044No.Factors pile defect distance point is not according to planmeanStd. devRan devQ9The lack of experience of the operator tool used.3.9330.5945Q13Not ratanya land surface area of the location of erection3.8670.6406Q15Less detailed determination of (erection sequence number)3,8000.6767Q14simulation plan drawing tool on erection3,7330.8848Q2Ignore the request and instruction owner3,7330.5949Q10Lack of teamwork and coordination of field workers3,6670,81610Q3quality assurance and quality control3,4000.91012Q12Pemancang tool that he was already old3,4000.98613Q14Lack of periodic checks construction3,3330.72414Q15Lack of periodic checks construction3,3330.72414Q16Corresponding coordinates stake3,3330.97615Q17Lack of expertise3,2000.77516	00	delays	4 000	1 105	2	
Q4procedures3.9330.7044No.Factors pile defect distance point is not according to planmeanStd. devRan devQ9The lack of experience of the operator tool used.3.9330.5945Q13Not ratanya land surface area of the location of erection3.8670.6406Q15Less detailed determination of the sequence As erection (erection sequence number)3,8000.6767Q14Simulation plan drawing tool on erection3,7330.8848Q2Ignore the request and instruction owner3,7330.5949Q10Lack of teamwork and coordination of field workers3,6670,81610Q3quality assurance and quality control3,6670.72411Q12Pemancang tool that he was already old3,4000.91012Q14Lack of periodic checks construction3,3330.72414Q15Less details Setting Out point corresponding coordinates stake3,3330.72414	Q٥	delays	4,000	1,195	3	
No.Factors pile defect distance point is not according to planmeanStd. devRan devQ9The lack of experience of the operator tool used.3.9330.5945Q13Not ratanya land surface area of the location of erection3.8670.6406Q15Less detailed determination of the sequence As erection (erection sequence number)3,8000.6767Q14Simulation plan drawing tool on erection3,7330.8848Q2Ignore the request and instruction owner3,7330.5949Q10Lack of teamwork and coordination of field workers3,6670,81610Q3quality assurance and quality control3,6670.72411Q12Pemacang tool that he was already old3,4000.91012Q14Lack of periodic checks construction3,3330.72414Q15Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3330.97615	01	Non-compliance and working	2 0 2 2	0.704	4	
No.Factors pile defect distance point is not according to planmean devStd. devRan devQ9The lack of experience of the operator tool used.3.9330.5945Q13Not ratanya land surface area of the location of erection3.8670.6406Q15Less detailed determination of (erection sequence number)3,8000.6767Q14Simulation plan drawing tool on erection3,7330.8848Q2Ignore the request and instruction owner3,7330.5949Q10Lack of teamwork and coordination of field workers3,6670,81610Q3quality assurance and quality control3,6670.72411Q12Pemancang tool that he was already old3,4000.91012Q14Lack of periodic checks construction3,3330.72414Q15Less details Setting Out point corresponding coordinates stake3,3330.72414	Q4	procedures	3.933	0.704	4	
point is not according to plandevkQ9The lack of experience of the operator tool used.3.9330.5945Q13Not ratanya land surface area of the location of erection3.8670.6406Q15Less detailed determination of (erection sequence number)3,8000.6767Q14Simulation plan drawing tool on erection3,7330.8848Q2Ignore the request and instruction owner3,7330.5949Q10Lack of teamwork and coordination of field workers3,6670,81610Q3quality assurance and quality control3,6670.72411Q12Pemancang tool that he was already old3,4000.91012Q14Lack of periodic checks during the process of construction3,3330.72414Q11Less details Setting Out point corresponding coordinates stake3,3330.97615Q11Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,2000,77516	No.		mean	Std.	Ran	
Q9The lack of experience of the operator tool used.3.9330.5945Q13Not ratanya land surface area of the location of erection3.8670.6406Q15Less detailed determination of the sequence As erection (erection sequence number)3,8000.6767Q14Simulation plan drawing tool on erection3,7330.8848Q2Ignore the request and instruction owner3,7330.5949Q10Lack of teamwork and coordination of field workers3,6670,81610Q3quality assurance and quality control3,6670.72411Q12Pemancang tool that he was already old3,4000.91012Q16Lack of periodic checks construction3,3330.72414Q17Less details Setting Out point corresponding coordinates stake3,3330.97615Q11Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,2000.77516					k	
Q9operator tool used.3.9530.5945Q13Not ratanya land surface area of the location of erection3.8670.6406Q15Less detailed determination of (erection sequence number)3,8000.6767Q14Simulation plan drawing tool on erection3,7330.8848Q2Ignore the request and instruction owner3,7330.5949Q10Lack of teamwork and coordination of field workers3,6670,81610Q3quality assurance and quality already old3,6670.72411Q12Pemancang tool that he was already old3,4000.91012Q16Lesk of periodic checks construction3,3330.72414Q16Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3000.97615					_	
Q13Not ratanya land surface area of the location of erection3.8670.6406Q15Less detailed determination of the sequence As erection (erection sequence number)3,8000.6767Q14The absence of maneuver simulation plan drawing tool on erection3,7330.8848Q2Ignore the request and instruction owner3,7330.5949Q10Lack of teamwork and coordination of field workers3,6670,81610Q3quality assurance and quality already old3,6670.72411Q12Pemancang tool that he was already old3,4000.91012Q16Lack of periodic checks construction3,3330.72414Q16Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3000.97615	Q9		3.933	0.594	5	
Q13of the location of erection3.8670.6406Q15Less detailed determination of the sequence As erection (erection sequence number)3,8000.6767Q14The absence of maneuver simulation plan drawing tool on erection3,7330.8848Q2Ignore the request and instruction owner3,7330.5949Q10Lack of teamwork and coordination of field workers3,6670,81610Q3quality assurance and quality control3,6670.72411Q12Pemancang tool that he was already old3,4000.91012Q16Corresponding coordinates construction3,3330.72414Q16Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3000.97615Q7Lack of expertise3,2000,77516						
Q15Less detailed determination of the sequence As erection (erection sequence number)3,8000.6767Q14The absence of maneuver simulation plan drawing tool on erection3,7330.8848Q2Ignore the request and instruction owner3,7330.5949Q10Lack of teamwork and coordination of field workers3,6670,81610Q3quality assurance and quality control3,6670.72411Q12Pemancang tool that he was already old3,4000.91012Q16Lack of periodic checks construction3,4000.98613Q16Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3330.72414Q11Lack of expertise3,3200.97615	Q13		3.867	0.640	6	
Q15the sequence As erection (erection sequence number)3,8000.6767Q14The absence of maneuver simulation plan drawing tool on erection3,7330.8848Q2Ignore the request and instruction owner3,7330.5949Q10Lack of teamwork and coordination of field workers3,6670,81610Q3quality assurance and quality control3,6670.72411Q12Pemancang tool that he was already old3,4000.91012Q1Lack of periodic checks during the process of construction3,3330.72414Q16Less details Setting Out point corresponding coordinates stake3,3330.72414Q11Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3000.97615Q7Lack of expertise3,2000,77516						
(erection sequence number)Image: construction of maneuver simulation plan drawing tool on erection3,7330.8848Q2Ignore the request and instruction owner3,7330.5949Q10Lack of teamwork and coordination of field workers3,6670,81610Q3Lack of commitment to quality assurance and quality control3,6670.72411Q12Pemancang tool that he was already old3,4000.91012Q1Lack of periodic checks during the process of construction3,4000.98613Q16Less details Setting Out point corresponding coordinates stake3,3330.72414Q11Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3330.97615	015		3 800	0.676	7	
Q14The absence of maneuver simulation plan drawing tool on erection3,7330.8848Q2Ignore the request and instruction owner3,7330.5949Q10Lack of teamwork and coordination of field workers3,6670,81610Q3Lack of commitment to quality assurance and quality control3,6670.72411Q12Pemancang tool that he was already old3,4000.91012Q1Lack of periodic checks during the process of construction3,4000.98613Q16Less details Setting Out point corresponding coordinates stake3,3330.72414Q11Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3000.97615	QIJ		5,000	0.070	,	
Q14simulation plan drawing tool on erection3,7330.8848Q2Ignore the request and instruction owner3,7330.5949Q10Lack of teamwork and coordination of field workers3,6670,81610Q3Lack of commitment to quality assurance and quality control3,6670.72411Q12Pemancang tool that he was already old3,4000.91012Q1Lack of periodic checks during the process of construction3,4000.98613Q16Less details Setting Out point corresponding coordinates stake3,3330.72414Q11Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3000.97615						
on erectionImage: state of the sequest and instruction owner3,7330.5949Q10Lack of teamwork and coordination of field workers3,6670,81610Q3Lack of commitment to quality assurance and quality control3,6670.72411Q12Pemancang tool that he was already old3,4000.91012Q1Lack of periodic checks during the process of construction3,4000.91012Q16Less details Setting Out point corresponding coordinates stake3,3330.72414Q11Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3000.97615	014		3 733	0.884	Q	
Q2Ignore the request and instruction owner3,7330.5949Q10Lack of teamwork and coordination of field workers3,6670,81610Q3Lack of commitment to quality assurance and quality control3,6670.72411Q12Pemancang tool that he was already old3,4000.91012Q1Lack of periodic checks during the process of construction3,4000.91012Q16Less details Setting Out point corresponding coordinates stake3,3330.72414Q11Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3000.97615	Q14		5,755	0.004	0	
Q2instruction owner3,7330.3949Q10Lack of teamwork and coordination of field workers3,6670,81610Q3Lack of commitment to quality assurance and quality control3,6670.72411Q12Pemancang tool that he was already old3,4000.91012Q1Lack of periodic checks during the process of construction3,4000.98613Q16Less details Setting Out point corresponding coordinates stake3,3330.72414Q11Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3000.97615						
Q10Lack of teamwork and coordination of field workers3,6670,81610Q3Lack of commitment to quality assurance and quality control3,6670.72411Q12Pemancang tool that he was already old3,4000.91012Q1Lack of periodic checks during the process of construction3,4000.91012Q16Less details Setting Out point corresponding coordinates stake3,3330.72414Q11Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3000.97615	Q2		3,733	0.594	9	
Q10coordination of field workers3,6670,81610Q3Lack of commitment to quality assurance and quality control3,6670.72411Q12Pemancang tool that he was already old3,4000.91012Q1Lack of periodic checks during the process of construction3,4000.98613Q16Less details Setting Out point corresponding coordinates stake3,3330.72414Q11Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3000.97615	-					
Coordination of field workersCoordination of field workersQ3Lack of commitment to quality assurance and quality control3,6670.72411Q12Pemancang tool that he was already old3,4000.91012Q1Lack of periodic checks during the process of construction3,4000.91012Q16Less details Setting Out point corresponding coordinates stake3,3330.72414Q11Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3000.97615	Q10		3,667	0.816	10	
Q3quality assurance and quality control3,6670.72411Q12Pemancang tool that he was already old3,4000.91012Q1Lack of periodic checks during the process of construction3,4000.98613Q16Less details Setting Out point corresponding coordinates stake3,3330.72414Q11Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3000.97615	-					
controlImage: controlQ12Pemancang tool that he was already old3,4000.91012Q1Lack of periodic checks during the process of construction3,4000.98613Q16Less details Setting Out point corresponding coordinates stake3,3330.72414Q11Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3030.97615Q7Lack of expertise3,2000,77516	~ ~		0.667	0.504	11	
Q12Pemancang tool that he was already old3,4000.91012Q1Lack of periodic checks during the process of construction3,4000.98613Q16Less details Setting Out point corresponding coordinates stake3,3330.72414Q11Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3030.97615	Q3		3,667	0.724		
Q12already old3,4000.91012Q1Lack of periodic checks during the process of construction3,4000.98613Q16Less details Setting Out point corresponding coordinates stake3,3330.72414Q11Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3330.97615Q7Lack of expertise3,2000.77516						
Already oldLack of periodic checksQ1Lack of periodic checksduring the process of construction3,400Q16Less details Setting Out point corresponding coordinates stake3,333Q17Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,333Q18O.724Q19Less details Setting Out point corresponding coordinates stake3,333Q11Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,303Q7Lack of expertise3,2000,775	012		3,400	0.910	12	
Q1during the process of construction3,4000.98613Q16Less details Setting Out point corresponding coordinates stake3,3330.72414Q11Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3330.97615Q7Lack of expertise3,2000.77516	X		2,.00	01910		
constructionImage: constructionQ16Less details Setting Out point corresponding coordinates stake3,3330.72414Q11Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3330.97615Q7Lack of expertise3,2000.77516						
Q16Less details Setting Out point corresponding coordinates stake3,3330.72414Q11Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3330.97615Q7Lack of expertise3,2000.77516	Q1		3,400	0.986	13	
Q16corresponding coordinates stake3,3330.72414Q11Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3330.97615Q7Lack of expertise3,2000.77516						
stakeQ11Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3330.97615O7Lack of expertise3,2000.77516		Less details Setting Out point				
Q11Pemacangan tool that treatment is less so the accuracy and precision are not appropriate3,3330.97615O7Lack of expertise3,2000.77516	Q16	corresponding coordinates	3,333	0.724	14	
Q11treatment is less so the accuracy and precision are not appropriate3,3330.97615O7Lack of expertise3,2000.77516						
Q11treatment is less so the accuracy and precision are not appropriate3,3330.97615O7Lack of expertise3,2000.77516		Pemacangan tool that				
accuracy and precision are not appropriate 07 Lack of expertise 3 200 0 775	011		2 2 2 2 2	0.076	15	
appropriate	νII	accuracy and precision are not	5,555	0.970	15	
O7 Lack of expertise 3 200 0 775 16						
	07	** *	2 200	0 775	16	
	Q/		3,200	0.775	10	

Table 4. Mean and Standard Deviation Factors defect within a
point of foundation




Fig 5:- Diagram of Mean - Standard Deviation distance point defect factor foundation

In the picture above shows that each variable groups in mean values between 3 and 4, so that it can be described average respondent answered quite agree and agree that each variable affects the defect of concrete pile foundation point distance is not according to plan.

D. Improve phase

In this phase of corrective actions related to recommendations based on the analysis that has been done before. Recommended action solution obtained from the interview to the specialist in providing alternative solutions on measures based on factors that influence.

D 1	
R.1	Check the cleanliness of working tools, formwork
	examination (form work), reinforcing checks,
	termination of casting.
R.2	To check the suitability of the design of the column
	before it closed formwork
R.3	Made a checklist and approval of desired material
	before pouring concrete
R.4	Made a checklist and approval of desired material
	before pouring concrete
R.5	Directed workers pouring concrete on procedures to
	manually or with mechanical vibrator
R.6	Coordinate with the provider of cast concrete to
	ensure the delivery schedule
R.7	Placing Concrete pump truck as close as possible to
	the casting area to avoid the risk of segregation
R.8	Make a schedule for maintenance work (Curing)

 Table 5. Recommendations for action to defect structure of porous concrete columns

R.1	Conducting surveys and uitzet point position foundation with project participants.
R.2	To check the suitability of the design of the column before it closed formwork
R.3	Using specialist subcontractors in the field of foundation
R.4	Doing permit stages include land preparation, material and equipment
R.5	Take measurements as auxiliary pole to point at a depth of 2 meters using waterpass / theodolite
R.6	Monitoring the pole axis eccentricity tolerance predefined

Table 6. The recommendations for action to defect within apoint of foundation

After getting a recommendation of remedial measures, the next step is done give the relationship between the causes and corrective action recommendations, the assessment is done by questionnaire and analyzed by the method of Quality Function Deployment (QFD).

• Relations with recommendations for action and the causes of defect structure of porous concrete columns

			Pacon	mond	ations	for ac	tion so	lutions	2
								e colun	
factor s defec t	mea n	R1	R2	R3	R4	R5	R6	R7	R8
Q16	4.13 3	1.6 7	1.3 3	1.0 0	2.3 3	9.0 0	2.3 3	1.6 7	-
Q15	4.06 7	1.6 7	1.0 0	3.6 7	1.6 7	3.6 7	1.6 7	7.0 0	I
Q14	4,00 0	5.0 0	9.0 0	1.6 7	1.6 7	3.6 7	-	0.3	0.3 3
Q9	4,00 0	2.3 3	7.0 0	1.6 7	9.0 0	9.0 0	1.0 0	1.6 7	5.0 0
Q17	3,80 0	9.0 0	2.3 3	2.3 3	1.0 0	5.0 0	2.0 0	5.0 0	-
Q4	3,80 0	9.0 0	9.0 0	9.0 0	7.0 0	7.0 0	1.0 0	1.6 7	9.0 0
Q7	3,73 3	3.3 3	7.0 0	7.0 0	7.0 0	3.0 0	9.0 0	7.0 0	9.0 0
Q13	3,66 7	7.0 0	2.3 3	0.3 3	0.6 7	0.6 7	0,0 0	0.3	-
Q12	3,66 7	0.6 7	0.6 7	0.6 7	0.6 7	1.6 7	0,0 0	0.6 7	2.0 0
Q10	3,60 0	3.6 7	5.0 0	2.3 3	3.6 7	3.0 0	1.6 7	1.6 7	5.0 0
Q3	3.53 3	9.0 0	9.0 0	5.0 0	2.3 3	2.3 3	7.0 0	5.0 0	7.0 0
Q18	3,33 3	1.6 7	1.0 0	1.0 0	7.0 0	5.0 0	9.0 0	3.0 0	0.6 7
Q2	3.13 3	5.0 0	4.3 3	5.0 0	4.3 3	5.0 0	5.0 0	1.6 7	5.0 0
								lutions e colun	
factor s	mea n	R1	R2	R3	R4	R5	R6	R7	R8

defec t									
Q6	3.13	1.6	2.3	7.0	1.6	1.0	2.3	0.6	1.6
	3	7	3	0	7	0	3	7	7
Q1	3.13	9.0	7.0	3.0	3.0	5.0	3.0	7.0	1.6
	3	0	0	0	0	0	0	0	7
Q11	3.13 3	1.0 0	0.6 7	1.6 7	1.6 7	7.0 0	-	1.6 7	0.3 3
Q8	3.13	4.3	2.3	1.6	9.0	2.3	9.0	5.0	5.0
	3	3	3	7	0	3	0	0	0
Q5	2,06	0.3	1.0	0.6	1.3	0.6	0.3	0.6	0.6
	7	3	0	7	3	7	3	7	7
total Score		26	26	19	22	26	18	18	185
		9	1.2	3.4	9.6	8.9	7.4	3.6	.6
Ranking Recommend ation		1	3	5	4	2	6	8	7

Table 7. Assessment and recommendations relationship factor defect structure of porous concrete columns

• Relations with recommendations for action and factor defect within a point of foundation

			Recommendations for action to defect pile distance point not according to plan						
factor s defec t	mea n	R1	R2	R3	R4	R5	R6		
Q6	4.06 7	9.00	9.00	5.00	9.00	2.33	4.33		
Q5	4,00 0	7.00	2.33	5.00	5.00	2.33	1.67		
Q8	4,00 0	7.00	2.33	5.00	7.00	5.00	4.33		
Q4	3.93 3	5.00	1.00	9.00	9.00	7.00	7.00		
Q9	3.93 3	1.67	1.67	9.00	5.00	7.00	3.67		
Q13	3.86 7	5.00	1.67	1.00	7.00	5.00	4.33		
Q15	3,80 0	2.33	9.00	1.00	1.67	1.67	1.67		
Q14	3,73 3	1.00	4.33	7.00	1.00	1.67	1.00		
Q2	3,73 3	1.67	5.00	5.00	7.00	5.00	5.00		
Q10	3,66 7	5.00	5.00	5.00	5.00	2.33	5.00		
Q3	3,66 7	1.00	2.33	1.67	4.33	3.67	7.00		
Q12	3,40 0	0.33	0.67	5.00	5.00	2.33	0.67		
Q1	3,40 0	5.00	2.33	2.33	5.00	3.67	7.00		
Q16	3,33 3	2.33	1.67	1.67	6,33	5.00	1.00		
Q11	3,33 3	0.33	0.67	6,33	7.00	4.33	0.67		

ISSN No:-2456-2165

Q7	3,20 0	1.67	5.00	7.00	2.33	5.00	1.67
total Score		211. 3	202. 1	282	323	233. 9	210
Ranking Recommend ation		4	6	2	1	3	5

 Table 8. Relationship factors and recommendation defect

 within a point of foundation

E. phase Control

The recommendations remedial measures useful for the next stage of the process work, in this study the results with recommendations for action on the improve phase is used to determine how much the probability of sigma level rise if the recommendations were calculated using monte carlo simulation.

1. Probability value of the minimum and maximum recommendations for action

Recommendati on	Minimum probabilit y sigma level	The maximum probability sigma level
R.1	0.416	0.605
R.2	0,404	0.587
R.3	0,299	0.435
R.4	0.355	0.516
R.5	0.416	0.605
R.6	0.290	0.421
R.7	0.284	0.413
R.8	0,287	0.417

Table 9. Min-max probability recommendationsdefect structure of porous concrete columns

Recommendati on	Minimum probabilit y sigma level	Maximum probability sigma level
R.1	0.546	0.763
R.2	0.530	0.741
R.3	0.393	0.549
R.4	0.466	0.652
R.5	0.546	0.763
R.6	0.380	0,532

Table 10. Min-max probability recommendation
defect within a point of foundation

2. Standard deviation and Absolute Error

Of the minimum and maximum value can be known the value of a standard deviation, and to seek absolute error then determined the expected relative error is 5%. Here are the results of the calculation are looking for absolute error:

Absolute error ($\boldsymbol{\varepsilon}$) = (Relative error) x (measured value) (2)

• Absolute error defect action on concrete columns:

$$(\mathbf{\hat{E}}) = 0.05 \text{ x } 3.375 = 0.169 \tag{3}$$

• Absolute error defect action recommendations within the foundation:

$$(\mathbf{\hat{E}}) = 0.05 \text{ x } 3.43 = 0.172 \tag{4}$$

3. Value Iteration

Value is the value of the loop iteration in which the number of iterations performed to determine the level of accuracy achievement sigma level.

• Calculation iteration defect on porous structure of concrete columns:

$$\frac{3x0,8838}{0,169}\Big)^2 = 245\tag{5}$$

iterati on	R.1	R.2	R.3	R.4	R.5	R.6	R.7	R.8	Amo unt
Min	0.4 15	0.4 03	0,2 99	0.3 55	0.4 15	0.2 89	0.2 83	0.2 86	2.75
Max	0.6 04	0.5 87	0.4 35	0.5 16	0.6 04	0.4 21	0.4 12	0.4 17	4.00
iterati on 1	0.4 74	0.4 69	0.3 26	0.4 53	0.5 01	0.3 19	0.3 52	0.2 95	3,192
iterati on 2	0.5 98	0.5 76	0.4 26	0.4 41	0.5 54	0.3 35	0.3 09	0.3 44	3,586
iterati	0.4	0.4	0.3	0.4	0.4	0.3	0.3	0.3	3,291

on 3	57	98	37	24	91	37	66	77	
iterati	0.4	0.5	0.3	0.4	0.5	0.4	0.3	0.3	3.374
on 4	91	20	35	30	33	05	00	57	5.574
									•••••
									•••••
iterati	0.5	0.4	0.2	0.4	0.5	0.2	0.4	0.4	
on	0.5	0.4	0,3	0.4	0.5	0.3	0.4	0.4	3.632
245	72	36	63	54	85	99	05	15	

Table 11. Iteration sigma level defect on porous structure of concrete columns

In the above table the known value of the iteration level to the sigma-245 is 3.63 this value can be achieved when the eighth recommendation do. In this study also simulate five scenarios with recommendations for action when the eight recommendations are not implemented fully in order to know sigma level of several scenarios.

		Recommendation implemented								
Scenario	R1	R2	R3	R4	R5	R6	R7	R8	sigm a	
scenario 1					~	~	~	~	3.15 8	
scenario 2	✓	✓	~	~					3.22 2	
scenario 3			✓	~	✓	~			3.18 5	
scenario 4	✓	✓					✓	~	3.19 5	
scenario 5	~	~	~	~	~	~	~	~	3,63 0	

 Table 12. Scenario recommendation defect structure of porous concrete columns




Fig 5:- Graph simulation scenario sigma level defect on porous structure of concrete columns

• Calculation iteration recommendations for action within a point defect piles not according to plan:

$$\left(\frac{3x0,806}{0,172}\right)^2 = 199\tag{6}$$

iteratio n	R.1	R.2	R.3	R.4	R.5	R.6	amou nt
Min	0.5 45	0.5 29	0,3 92	0.4 65	0.5 45	0.3 80	2,86
Max	0.7 63	0.7 41	0,5 48	0.6 51	0.7 63	0,5 31	4.00
iteratio n 1	0.6 03	0.6 55	0.4 72	0.5 43	0.5 73	0,5 09	3.35
iteratio n 2	0,6 29	0.6 31	0.4 10	0.6 26	0.6 34	0.4 54	3.38
iteratio n 3	0.7 09	0.6 04	0,4 07	0.5 33	0.5 53	0.5 08	3.317
			······ ·		······ ·		
			·····	·····	······ ·	·····	
			·····	·····	·····	·····	
	······ ·	······ ·	·····	·····	······ ·	·····	
iteratio n 199	0.5 80	0.6 16	0.4 87	0.6 49	0.6 52	0.5 03	3.48

Table 12. Iteration sigma level Recommendations defect within a point of foundation

In the above table the known value of the iteration level to the sigma-199 was 3.48 this value can be achieved when the sixth recommendation do. In this study also simulated four scenarios on the eighth course of action if they are not implemented fully in order to know sigma level of several scenarios.

Guardia		Recommendation implemented						
Scenario	R1	R2	R3	R4	R5	R6	sigm a	
scenario 1	~	~	~	~			3.27 9	
scenario 2			~	~	~	~	3.24 7	
scenario 3		~	~	~	~		3.27 9	
scenario 4	~	~	~	~	~	~	3,48 0	

 Table 13. Scenario recommendation defect within a point of foundation




Fig 6:- Graph simulation scenario sigma level recommendations within point defect foundation

V. CONCLUSION

Defect construction work under three-sigma level defect column structure of porous concrete work with sigma level of 2.75 and the distance point of the foundation is not in accordance with the plan sigma level of 2.86. Both types of defects are located below the average for the construction industry. Factors that influence the occurrence of defects porous concrete column structure as much as 18 variables, and the factors that most influence is less than perfect compaction factor when casting. For factors that influence the occurrence of a point defect within the foundation is not according to plan as much as 16 variables and the most influencing factor is lack komunakasi with planning consultant and owner. In the simulation scenario action recommendations to improve the sigma level in order to be at level three.

BIBLIOGRAPHY

- Ahzahar, N., Karim, N., Hassan, S., & Eman, J. (2011). A Study of Contribution Factors to Building Failures and Defects in Construction Industry. Procedia Engineering, 20 (20), 249-255.
- [2] Aljassmi, H., & Han, S. (2013). Analysis of Causes of Construction Defects Using Fault Trees and Risk Importance Measures. Construction Engineering and Management, 139 (139), 870-880.
- [3] Apriani, DN (2009). Product Quality Issues Analysis In Real Estate Developer Company Method Using Six

ISSN No:-2456-2165

Sigma. Jakarta: Faculty of Science and Technology State Islamic University Syarif Hidayatullah.

- [4] Barrett, K. (2008). Defective Construction Work. United Kingdom: Wiley Blackwell.
- [5] Buys, F., & Roux, M. I. (2010). Causes of defects in the South African housing construction industry: Perceptions of the built-environment stakeholders. Oorsigartikels, 78-99.
- [6] Chong, W.-K., & Low, S.-P. (2006). Building Latent Defects: Causes and Design Strategies to Prevent Them. Journal of Performance of Constructed Facilities, 20, 213.
- [7] Coskun, A. (2011). Six Sigma Projects and Personal Experiences. In VN S, Lean Six Sigma (pp. 1-24). India: Intech.
- [8] Femi, OT (2014). Effects Of Faulty Construction On Building Maintenance. International Journal of Technology Enhancements and Emerging Engineering Research, 2 (3), 73-79.
- [9] Forcada, N., Macarulla, M., Gangolells, M., & Casals, M. (2014). Assessment of construction defects in residential buildings in Spain. Building Research & Information, 42 (42), 629-640.
- [10] Bryan Garner. (1999). Black "s Law Dictionary (7th edition).Unite State of America: West Group.
- [11] Gaspersz, V. (2005). Total Quality Management. Jakarta: PT Gramedia Pustaka Utama.
- [12] Gatlin, F. (2013). Identifying and Managing Design And Construction Defect. Chicago: Insight from Hindsight.
- [13] Hassanain, M., Al-Ofi, AK, & Al-Abdullah, A. (2013). Factors affecting maintenance cost of hospital facilities in Saudi Arabia. Property Management, 31, 297-310.
- [14] Hidayatno, A., & Afriansyah, B. (2004). Cut Quality Improvement Tracer Eye Engineering at PT. United Tractors Pandu Engineering Method with Six Sigma. Technology Journal Special Edition 2: Mechanical Industry, 1-11.
- [15] Kiran, DR (2017). Total Quality Management Key Concepts and Case Studies. India: BSP Books Pvt.
- [16] Knowles, G. (2011). Six Sigma. Bookboon.
- [17] Knowledge and Experience (2010). ISO 9000: 2005 Terms and Definitions. Retrieved December 27, 2017, from <u>http://www.expert9001.ro</u>.
- [18] Lester, A. (2017). Project Management, Planning and Control. Cambridge: Butterworth-Heinemann.
- [19] Merhaba, B. (2015). Study of Construction Defects in Public Building Projects in Addis Ababa. Addis Ababa University.
- [20] Mills, A., Love, PE, & Williams, P. (2009). Costs in Residential Construction Defect. Journal of Construction Engineering and Management, 135 (135), 12-16.
- [21] Montgomery, D. (2009). Introduction to Statiscal Quality Control. United States of America: Don Fowley.
- [22] Nayanthara, d. S., & Ranasinghe, M. (2010). Maintainability risks of condominiums in Sri Lanka. Journal of Financial Management of Property and Construction, 15, 41-60.
- [23] Piasny, J., & Pasławski, J. (2014). Methodology to Identify The Causes Of The Consequences of Defect in Building Constructions. Institute of Structural Engineering, Faculty of Civil and Environmental Engineering, Poznań University of Technology, 184-193.

- [24] Pyzdek, T. (2003). The Six Sigma Handbook. United States of America: The McGraw HIII Companies.
- [25] Rao, A. (1998). Total Quality Management, A Cross functional Perspective. Canada: John Wiley & Sonc Inc.
- [26] Razak, MA, & Jaafar, M. (2012). Assessment on Faulty Public Hospital Design in Malaysia. Journal Design + Built, 5.
- [27] Reason, J. (1990). Human error. Cambridge University Press: Cambridge, UK.
- [28] Republika. (2017). Larger Development Budget, budget Assessed Ideal Surabaya. Surabaya:<u>http://www.republika.co.id</u>,
- [29] Indonesia.2017.Undang Republic Act No.2 of 2017 on State Kontruksi.Lembaran Services RI.Sekretariat Negara.Jakarta.
- [30] Indonesia.2000 Republic. Government Regulation 29 Year 2000 concerning the State Kontruksi.Lembaran Services RI.Sekretariat Negara.Jakarta.
- [31] Sabha, FA (2015). The Effect of Design and Construction's Faults / Errors n Maintenance of UNRWA's School Buildings in the Gaza Strip. 2015: The Islamic University - Gaza Higher Education Deanship.
- [32] Shirkavand, I., Lohne, J., & Laedre, O. (2016). Defects at handover in Norwegian construction projects. Social and Behavioral Sciences, 226 (226), 3-11.
- [33] Sik Park, C., Yeop Lee, D., Seong Kwon, O., & Wang, X. (2013). A framework for proactive management of construction defect using BIM, augmented reality and ontology-based data collection template. Automation in Construction, 33, 61-71.
- [34] Sun. (2014). Ask the contractor Naughty Council prohibited Participate 2014. Project Tender Surabaya:<u>http://surabaya.tribunnews.com</u>.
- [35] Tchidi, MF, He, Z., & Li, YB (2012). Process and Quality Improvement Using Six Sigma in Construction Industry. Journal of Civil Engineering and Management, 158-172.
- [36] Wahyono, HL (2011). Failure Analysis Incompatibility Contract In Construction And Building Failure. Semarang: Post Graduate University Dipeonegoro.